EXHIBIT 2

GM 2014 YEAR-TO-DATE NORTH AMERICAN RECALLS INCLUDING EXPORTS

1 2 3 4 5 6 7 8 9	1/13 1/23 2/20 2/25 3/17 3/17	2014 Chevrolet Silverado and GMC Sierra full-size pickups 2014 Chevrolet Trax/Tracker (Mexico and export only) 2014 Buick Enclave, LaCrosse, Regal, and Verano; 2014 Chevrolet Cruze, Impala, Malibu and Traverse, GMC Acadia 2005-07 Chevrolet Cobalt; 2006-207 Pontiac Pursuit; 2003-07 Saturn ION; 2006-07 Chevrolet HHR and Pontiac Solstice; 2007 Saturn Sky, Opel/Yauxhall GT,	Overheated Exhaust Components Fuel Line Quick Connector Transmission Shift Cable Adjuster Body Fractures (NC) Ignition Switch Torque Performance	324,970 0 355	377,88 2,06
4 5 6 7 8 9	2/25 3/17 3/17	2014 Chevrolet Cruze, Impala, Malibu and Traverse, GMC Acadia 2005-07 Chevrolet Cobalt; 2006-2007 Pontiac Pursuit; 2003-07 Saturn ION; 2006-07 Chevrolet HHR and	Body Fractures (NC)		38.
6 7 8 9	3/17	Pontiac Solstice: 2007 Saturn Sky, Opel/Vauxhall GT,	agricion station lorque Periormance	1,367,146	1,620,66
6 7 8 9	3/17	Daewoo G2X and Pontiac G5			
7 8 9		2013-14 Cadillac XTS	Brake Vacuum Booster Pump Vent and Connector	63,903	66,21
9		2009-14 Chevrolet Express and GMC Savana 2008-13 Buick Enclave, Chevrolet Traverse, GMC Acadia,	Front Passenger Airbag Performance (NC) Side Impact Airbag Connector	303,013 1,176,407	354,55 1,334,98
10	3/28	Saturn Outlook 2014 Cadillac ELR	Electronic Brake Control Module Calibration	656	66
11	3/28	2008-11 Chevrolet HHR; 2008-10 Chevrolet Cobalt; 2008-10 Pontiac G5; 2008-10 Pontiac Solstice; 2008-10 Saturn Sky; 2008-10 Opel GT; 2008-09 Daewoo G2X	Ignition Switch Torque Performance	823,788	970,74
	3/28	2013 and 2014 MY Chevrolet Cruze models equipped with 1.4L turbocharged engine (RPO LUV)	Half Shaft Fracture	174,046	197,32
12	3/28	2014-15 full-size trucks and full-size utilities	Oil Cooler Fitting	489,936	559,249
	3/31	with MYC transmission 2004-06 Chevrolet Malibu/Malibu Maxx, Pontiac G6; 2004-07 Saturn ION; 2008-09 Chevrolet Malibu, Pontiac G6, Saturn Aura; 2010 Cobalt; 2009-10 Chevrolet	Electronic Power Steering	1,340,447	1,508,44
13	4/9	HHR; Previous EPS Recall Service Parts 2005-2010 Chevrolet Cobalt; 2006-2011 Chevrolet HHR; 2006-2010 Pontiac Solstice; 2003-2007 Saturn ION; 2007-2010 Saturn Sky and Pontiac GS	Ignition Cylinder	2,191,014	2,591,40
14 15	4/19	2009-2010 Pontiac Vibe 2013 Cadillac SRX	Air Bags (Toyota) Hesitation	23,249 50,571	40,51 56,36
16	4/24	2015 Chevrolet Silverado HD and GMC Sierra HD	Diesel Transfer Pump	50,571	50,30
17	4/29	2014 Chevrolet Traverse, GMC Acadia and Buick Enclave 2007-2008 Saturn Aura	Inaccurate Fuel Gauge Shift Cable	51,640 56,214	57,13 59,62
.0	5/19	2004-2008 Saturn Aura 2004-2008 Chevrolet Malibu; 2005-2008 Pontiac G6	Shift Cable	1,074,932	1,215,79
19	5/7	2014 Chevrolet Malibu and Buick LaCrosse	Brake Rotors	8,208	8,59
20 21	5/13 5/13	2014 Chevrolet Malibu and Buick LaCrosse 2014 Chevrolet Silverado and GMC Sierra Light Duty;	Brake Boost (NC) Tie-rods	140,067 477	144,78 52
22	5/14	2015 Chevrolet Tahoe 2005-2007 Chevrolet Corvette	Low Beams	103,158	111,88
23	5/14	2014 Cadillac CTS	Wipers	19,225	21,56
24	5/14	2004-2012 Chevrolet Malibu; 2004-2007 Malibu Maxx; 2005-2010 Pontiac G6; 2007-2010 Saturn Aura	Brake Lamps	2,440,524	2,703,65
25 26	5/16	2015 Cadillac Escalade	Passenger Air Bag (NC)	1,402	1,53
	5/19	2009-2010 Saturn Outlook; 2009-2014 Chevrolet Traverse, GMC Acadia and Buick Enclave	Front Seat Belts	1,339,355	1,509,52
27 28	5/19 5/21	2015 Chevrolet Silverado HD and GMC Sierra HD 2004-2008 Chevrolet Aveo; 2005-2008 Pontiac Wave, G3	Loose Fuse Block Daytime Running Lamps	58 217,454	284,69
29 30	5/21 5/30	2004-2008 Chevrolet Optra (imported from GM Korea; sold in U.S. Territories) Certain 2014 Chevrolet Silverado and GMC Sierra; 2015 Chevrolet Tahoe and Suburban, GMC Yukon and Yukon XL	Daytime Running Lamps Sensing and Diagnostic Module	214 334	21
31	5/30	and Cadillac Escalade and Escalade ESV Certain 2014 Chevrolet Silverado LD; 2014 GMC Sierra LD; 2015 Chevrolet Silverado HD; Tahoe and Suburban and GMC Sierra HD, Yukon and Yukon XL	Base Radio Chime (NC)	57,512	69,55
32	5/30	Certain 2013 and 2014 Chevrolet Spark and 2013 Buick Encore	Passenger Air Bag	61	8
33 34	5/30	Certain 2012 Chevrolet Cruze, Camaro, Sonic and Buick Verano 2014 Chevrolet Corvette	Driver's Air Bag Shorting Bar Sensing and Diagnostic Module	31,520 33	36,01
35	6/11	2004-2011 Saab 9-3 Convertible	Seat Belt Retractor	28,789	29,75
36 37	6/11	2012 Chevrolet Sonic 2014 Buick LaCrosse	Transmission Turbine Shaft Fracture Driver's Door Wiring Splice (NC)	21,567 14,765	24,90 15,18
38	6/13	2010-2014 Chevrolet Camaro	Key FOB Can Bump Ignition	464,712	511,52
39	6/16	2005-2009 Buick Allure and LaCrosse; 2006-2014 Chevrolet Impala; 2000-2005 Cadillac Deville; 2004-2011 Cadillac DTS; 2006-2011 Buick Lucerne; 2006-2007 Chevrolet Monte Carlo	Key Replacement from Slot to Hole	3,140,725	3,340,55
40 41	6/16	2013-2014 Cadillac ATS and 2014 Cadillac CTS	Shift Cable	90,750	109,03
	6/16	2015 Chevrolet Silverado 2500/3500 HD and GMC Sierra 2500/3500 HD	Steering Pump Clamp Inspection	124,527	141,26
42 43	6/16	2011 Cadillac AWD CTS 2014 Chevrolet Corvette with Competition Sport Seats	Gasket Leak Air Bags	16,932 712	18,27 96
44 45	6/16 6/27	2014-2015 Chevrolet Silverado and GMC Sierra 2014-15 Chevrolet Silverado and GMC Sierra; 2015 Chevrolet Suburban and Tahoe, GMC Yukon	Unsecured Floor Mats 4WD Transfer Case	184 392,459	18 466,94
46	6/27	and Yukon XL with 4WD 2013-14 Chevrolet Cruze	Driver Air Bag	29,019	33,08
47 48	6/27	2013-14 Chevrolet Caprice Police; 2014 Chevrolet SS	Windshield Wiper Module	4,794	4,79
49	6/27	2014 Chevrolet Corvettes with the FE1 or FE3 suspension 1997-2005 Chevrolet Mailibu; 1998-2002 Oldsmobile Intrigue; 1999-2004 Oldsmobile Alero; 1999-2005 Pontiac Grand Am; 2000-2005 Chevrolet Impala and Monte Carlo;	Rear Shock Weld Unintended Ignition Key Rotation	1,939 5,877,818	2,05 6,584,85
50	6/30	2004-2008 Pontiac Grand Prix 2003-2014 Cadillac CTS, 2004-2006 Cadillac SRX (2014 models are derivative models in previous generation body style; 2014 CTS sedan not involved)	Unintended Ignition Key Rotation	554,328	616,17
51	6/30	2011-2014 Chevrolet Cruze; 2012-2014 Chevrolet Sonic; 2013-2014 Chevrolet Trax, Buick Encore and Verano	Engine Block Heater Power Cord	2,990	20,13
52 53	6/30	2014 Chevrolet Camaro and Impala, Buick Regal, Cadillac XTS	"Superhold" Joint Fastener Torque	106	11
54	6/30	2007-11 Chevrolet Silverado HD, GMC Sierra HD equipped with an auxiliary battery 2005-2007 Buick Rainier, Chevrolet TrailBlazer, GMC Envoy, Isuzu Ascender, Saab 9-7x;	Auxiliary Battery Underhood Fusible Link Driver's Door Module for Power Locks and Window Switches	9,371 181,984	188,70
55	7/18	2006 Chevrolet TrailBlazer EXT, GMC Envoy XI. 2014-2015 Chevrolet Spark	Lower Control Arm Ball Joint	1,919	3,0€
56	7/21	2013 Chevrolet Malibu; 2011-2013 Buick Regal	Front Turn Signal Bulbs	120,426	127,23
57 58	7/22	2015 Chevrolet Tahoe and Suburban, GMC Yukon and Yukon XL 2014 Chevrolet Impala	Roof Rail Air Bag Electronic Power Steering	22 57,242	65,27
59	7/22	2010-2012 Chevrolet Equinox, GMC Terrain and Cadillac SRX 2011-2012 Chevrolet Camaro, Buick Regal and LaCrosse	Power Height Adjustable Seats	414,333	475,16
50	7/22	2013-2014 Buick Encore and Cadillac ATS; 2014 Cadillac CTS and ELR, Chevrolet SS, Caprice, Caprice PPV and Silverado 1500 and GMC Sierra 1500;	Seat Hook Weld Incomplete	124,007	151,92
61	7/28	2015 Chevrolet Silverado 2500/3500 HD and GMC Sierra 2500/3500 HD 2007 Chevrolet Optra (Canada); 2009-2010 Chevrolet Aveo;	Reduced Brake Performance	1,968	2,05
52	8/7	2009 Pontiac G3/Wave 2013 Cadillac ATS, Chevrolet Trax (Canada) and	Frontal Lapbelt Pretensioners	48,059	72,82
63	8/7	Buick Encore (Imported) 2002-2004 Saturn Vue	Ignition Key Pullout in Run Position	202,155	215,24
54	8/7	2013-2014 Cadillac ATS (Export Only)	Front Exterior Lighting (NC)	0	3,62
65 66	8/7	2014-2015 Chevrolet Impala 2011-2014 Chevrolet Express and GMC Savana	Console Bin Door Latch (NC) CNG High Pressure Regulator Leak	14,940 3,196	15,38 3,20
57	8/20	2013-2014 Cadillac SRX; 2014 Chevrolet Impala	Sensing and Diagnostic Module	5	
58	8/29	2011-2013 Chevrolet Caprice Police Patrol Vehicles	Transmission Selector Roll and Selector Pin Displacement (NC)	7,598	7,60
69 70	9/4	2004-2007 Cadillac CTS-V; 2006-2007 Cadillac STS-V 2008-2009 Pontiac G8; 2011-2013 Chevrolet Caprice	Overheating Fuel Pump Module Unintended Ignition Key Rotation	10,005 47,225	10,49 50,09
71	9/4	2014 Chevrolet Sonic	Steering Column Electrical Connection	304	33
72 73	9/4 9/17	2013-2015 Cadillac XTS; 2014-2015 Chevrolet Impala 2010-2015 Cadillac SRX; 2011-2012 Saab 9-4X	Emergency Brake Drag (NC) Rear Suspension Nut Torqueing	205,309 290,107	221,55 430,55
74	9/17	2014 Chevrolet Corvette	Driver's Air Bag Center Plate Fracture	89	9
75 76	9/17 9/23	2015 Chevrolet Corvette 2013-2015 Chevrolet Spark and Spark EV	Parking Brake Cable (NC) Hood Latch Corrosion (NC)	783 89,294	93,83
77	10/1	2013-2014 Chevrolet Tahoe and Suburban, Cadillac CTS, Escalade and Escalade ESV, GMC Yukon and Yukon XL; 2014 Chevrolet Traverse. Express and Silverado HD. GMC Acadia.	Chassis Control Module Contamination	106,307	126,41
78	10/7	Savana and Sierra HD, and Buick Enclave 2015 Cadillac Escalade	Passenger Air Bag Cover	1,039	1,14
79 80	10/9	2015 Chevrolet Colorado and GMC Canyon	Air Bag Wiring	2,283	2,43
50	11/25	2006-2009 Buick LaCrosse; 2006-2007 Chevrolet TrailBlazer, GMC Envoy and Buick Rainier; 2006 Chevrolet TrailBlazer EXT and GMC Envoy XL; 2006-2008 Saab 9-7X and Isuzu Ascender	Headlamp Driving Module Failure	273,182	316,35